

Taric code: 3822 00 00

# Specifications

concentration..... 1000 mg/l

Danger

This standard solution is traceable to Standard Reference Material from NIST.

# Physical data

• Density: 0,98 g/cm<sup>3</sup>

## Safety - GHS

Signal Word:

### Hazard Statements:

H315: Causes skin irritation. H318: Causes serious eye damage.

#### **Precautionary Statements:**

P280: Wear protective gloves / protective clothing / eye protection / face protection. P264: Wash thoroughly after handling. P305+P351+P338: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. P310: Immediately call a POISON CENTER or doctor / physician. P321: Specific treatment (see on this label). P332+P313: If skin irritation occurs: Get medical advice / attention.

## Transport/storage

• UN - • UN - • UN - • 10°C - 30°C